

# Third Party Sensor Adapter

**Connect sensors with 0-5 VDC output.**

**Connect Dry Contacts which require 5VDC power**

The Sensor Adapter makes it easy to connect third party sensors that output a 0-10 DC Voltage scale.

A switch on the side of the sensor adapter allows you to switch to a dry contact I/O instead, which is capable of maintaining a 5VDC output to power the sensor at all times, while still monitoring the dry contact input.

